



AN AIRBUS COMPANY

NOTIFICATION BULLETIN

NAVBLUE Reference: 2310-02N

Notification Published date: 19-10-2023

Product Affected: Navigation+

AIRAC Cycle: 2310

Effective Date: 05-10-2023

Region: AFR

Country: Libya

Subject: ENR Waypoint changes affecting the SID/STARs at HLLS and HLLB

Source: AIRAC Amd 01/23

SEBHA INTERNATIONAL (HLLS):

Please Note: AIRAC AIP Amd 01/23 removes the waypoint BRACK from ENR 4.4. and adds a new collocated waypoint BOXAL. The respective procedures where the waypoint is part of the route have not been updated by the state. The following changes have been made for these procedures in **NAVBLUE** databases for 2310 cycle.

SIDs

BRACK 1C renamed BOXAL 1C.

BRACK 1F renamed BOXAL 1F.

STARs

BRACK 1A renamed BOXAL 1A.

BRACK 1B renamed BOXAL 1B.

BRACK 1D renamed BOXAL 1D.

BRACK 1E renamed BOXAL 1E.

BENGAZI/BENINA INTERNATIONAL (HLLB):

Please note: AIRAC AIP Amd 01/23 removes the waypoint RZAAM and PRAWN from ENR 4.4. and adds a new collocated waypoint RIGEM and PEBAN. The respective procedures where waypoint is part of the route have not updated by the state. The following changes have been made for these procedures in **NAVBLUE** databases for 2310 cycle



AN AIRBUS COMPANY

NOTIFICATION BULLETIN

SIDs

RZAAM 1C renamed RIGEM 1C.
RZAAM 1F renamed RIGEM 1F.
PRAWN 1C renamed PEBAN 1C.
PRAWN 1F renamed PEBAN 1F.

STARs

RZAAM 1A renamed RIGEM 1A.
RZAAM 1B renamed RIGEM 1B.
RZAAM 1D renamed RIGEM 1D.
RZAAM 1E renamed RIGEM 1E.
PRAWN 1A renamed PEBAN 1A.
PRAWN 1B renamed PEBAN 1B.
PRAWN 1D renamed PEBAN 1D.
PRAWN 1E renamed PEBAN 1E.