



AN AIRBUS COMPANY

OMITTED NOTIFICATION BULLETIN

NAVBLUE Reference: 2310-01O

Notification Published date: 27-09-2023

Product Affected: Navigation+

Please note that the following information has not been incorporated into NAVBLUE databases for cycle 2310

The below information is under state query and has been omitted from NAVBLUE databases until the query has been resolved.

Source: Democratic Republic of Congo (FZNP) AIP amendment 4/20

NOT IN NAVBLUE DATABASES:

The change of THR coordinates on RWY 11/29 at FZNP has not been included in Navblue databases due to an outstanding state query.

is awaiting state information clarification.

Source: Mauritania (GQNS) ASECNA AIP amendment 11/20

NOT IN NAVBLUE DATABASES:

The RWY length of 1600m for RWY 06/24 at GQNS has not been included in Navblue databases due to an outstanding state query.

is awaiting state information clarification.

Source: Papua New Guinea (AYTB) Flight Supplement 210715 and NOTAM A0054/22

NOT IN NAVBLUE DATABASES:

Approach procedure NDB/DME (via OKT) CLOUDBREAK – Due to the relocation of Navaid by NOTAM and state has not revised this approach procedure based on the new location of OKT NDB/DME.

is awaiting state information clarification.

Source: Sudan AIRAC AIP Amd 01/22

NOT IN NAVBLUE DATABASES:

Changes to the direction of the segment KAFIA-ALMAM on airway A410 due to an



AN AIRBUS COMPANY

OMITTED NOTIFICATION BULLETIN

outstanding state query

is awaiting state information clarification.

Source: Australia (YPDN) AIRAC AIP Supplement H42/22

NOT IN NAVBLUE DATABASES:

YPDN Approaches RNP X RWY 11, RNP X RWY 29, RNP Y RWY 11 and RNP Y RWY 29 have been omitted due to the arc centre fix coordinates not being published.

is awaiting state information clarification.

Source: Botswana AIP Amd 01/22

NOT IN NAVBLUE DATABASES:

Please note that airport FRANCISTOWN/ P G MATANTE has been published with ICAO Code FBPM due to an ongoing query with the state. The ICAO code has also been mentioned in documentation as FBPT, we wait for confirmation from the state.

is awaiting state information clarification.

Source: Democratic Republic of Congo AIP AMD 01/23

NOT IN NAVBLUE DATABASES:

Due to pending state query the updates on page ENR3.5-9 for published airways ATS32 and possible removal of airways ATS29, ATS30, ATS31 have not been actioned in the database.

is awaiting state information clarification.

Source: Switzerland (LSZA)

NOT IN NAVBLUE DATABASES:

Due to VOR/DME BEG being withdrawn by Italy (AIRAC AMD 02-23) the following procedures have been removed from NAVBLUE databases:

SIDs ORI1W & ORIIU

STARs LUSI7L, LUSI7P, ORI7L & ORI7P

is awaiting state information clarification.

Source: Rwanda (HRZA) AIRAC AMD 02/23



AN AIRBUS COMPANY

OMITTED NOTIFICATION BULLETIN

NOT IN NAVBLUE DATABASES:

RNAV RWY 20 approach has not been added to the NAVBLUE databases due to the state not publishing the coordinates for the waypoint IF20.

is awaiting state information clarification.

Source: Paraguay (SGAS) AIRAC AIP AMD 01-23

NOT IN NAVBLUE DATABASES:

SIDs EDRAV and KONTO waypoint AS207 (+FL220) has not been included due to the state publishing incorrect coordinates.

is awaiting state information clarification.