



AN AIRBUS COMPANY

NOTIFICATION BULLETIN

NAVBLUE Reference: 2312-03N

Notification Published date: 29-11-2023

Product Affected: Navigation+

AIRAC Cycle: 2312

Effective Date: 30-11-2023

Region: SPA

Country: Australia

Subject: Brisbane International Airport (YBBN)

Source: AIRAC Supp H88-23

RWY 01R and RWY 19L Temporary Approach Procedures :

Caution

Brisbane airport will be conducting runway maintenance works that require temporary threshold displacements of RWY 01R by 921M and RWY 19L by 889M. **A NOTAM will be issued to indicate when the threshold is displaced.** New RNP APCH and RNP AR approach procedures have been designed for use during the airport runway works. The RNP APCH approach procedures have the suffix 'T' and the RNP AR have suffixes "R" and "S".

RWY 01C and 19C has been added to the Navigation Database to reflect the temporary threshold displacements of 01R/19L. Temporary IACs (T, R and S) and STARs slaved to RWY 01C/19C should be used when a NOTAM indicates the threshold is displaced.