



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2312-04E

Notification Published date: 04-12-2023

Product Affected: Navigation+

AIRAC Cycle: 2312

Effective Date: 30-11-2023

Region: SPA

Country: Australia

Subject: SYDNEY/KINGSFORD SMITH INTERNATIONAL (YSSY)

Source: AIRAC Amd DAP East A177-23

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2312

Caution

Please note that for SID procedure KAMPI 6 In RIC transition, the termination fix RIC TACAN (VHF) is INCORRECT IN NAVBLUE DATABASE. The termination fix for RIC transition should be RIC NDB (347 KHZ) instead of RIC TACAN (VHF).

These changes will be incorporated in NAVBLUE databases for cycle 2313