



AN AIRBUS COMPANY

LATE SOURCE NOTIFICATION BULLETIN

NAVBLUE Reference: 2406-04L

Notification Published date: 06-06-2024

Product Affected: Navigation+

AIRAC Cycle: 2406

Effective Date: 13-06-2024

Region: EUR

Country: Germany; United Kingdom

Subject: Multiple Aerodrome Changes

Source: Germany VFR AIP AMD 06-24; United Kingdom MIL AIRAC AMD 06-24

Please note that the following information was received too late to be incorporated into NAVBLUE databases for cycle 2406

Germany VFR AIP AMD 06-24

ATTENDORN-FINNENTROP (EDKU):

Airport: Mag var changed from 2°E to 3°E

BINNINGEN (EDSI):

Airport: Mag var changed from 3°E to 4°E

RWY 06: RWY 06- Mag bearing changed from 63° to 62°.

RWY 24: Mag bearing changed from 243° to 242°.

HALLE-OPPIN (EDAQ):

Airport: Mag var changed from 3°E to 5°E

RWY 11: Mag bearing changed from 111° to 109°

RWY 29: Mag bearing changed from 291° to 289°.

Airport comms: 135.155 RDO call sign changed from OPPIN INFO to OPPIN RADIO.

NEUBURG-EGWEIL (EDNJ):

Airport comms: 132.005 RDO callsign changed from EGWEIL INFO to EGWEIL RADIO.

OFFENBURG (EDTO):

Airport: Mag var changed from 2°E to 3°E.

Airport comms: 132.04 RDO callsign changed from OFFENBURG INFO to OFFENBURG RADIO.

PFARRKIRCHEN (EDNP):

Airport: Mag var changed from 3°E to 5°E.

Airport comms: 119.98 RDO callsign changed from PFARRKIRCHEN INFO to PFARRKIRCHEN RADIO.



AN AIRBUS COMPANY

LATE SOURCE NOTIFICATION BULLETIN

PIRNA PRATZSCHWITZ (EDAR):

Airport: Mag var changed from 3°E to 5°E.

RWY 11/29: RWY ID changed from 12/30 to 11/29.

RWY 11: Mag bearing changed from 120° to 113°.

RWY 29: Mag bearing changed from 300° to 293°.

Airport comms: 118.630 RDO callsign changed from PIRNA INFO to PIRNA RADIO.

PURKSHOF (EDCX):

Airport: Mag var changed from 4°E to 5°E

Airport comms: 135.005 RDO callsign changed from PURKSHOF INFO to PURKSHOF RADIO.

SONNEN (EDPS):

Airport: Mag var changed from 3°E to 5°E

Airport comms: 118.96 RDO callsign changed from SONNEN INFO to SONNEN RADIO

VILSHOFEN (EDMV):

Airport: Mag var changed from 4° to 5°E

RWY 12: Mag bearing changed from 117° to 116°

RWY 30: Mag bearing changed from 297° to 296°.

Airport comms: 119.18 RDO callsign changed from VILSHOFEN INFO to VILSHOFEN RADIO.

United Kingdom MIL AIRAC AMD 06/24:

MARHAM (EGYM):

Airport Comms

WADDINGTON (EGXW):

Airport: Magnetic variation changed from 0°E to 1°E

ILS 20 IWA: Loc bearing changed from 204° to 203°; station declination changed from 0°E to 1°E

ILS DME 20 IWA: station declination changed from 0°E to 1°E

WATTISHAM (EGUW):

Airport Comms

These changes will be incorporated in NAVBLUE databases for cycle 2407