



AN AIRBUS COMPANY

## OMITTED NOTIFICATION BULLETIN

**NAVBLUE Reference:** 2406-010

**Notification Published date:** 05-06-2024

**Product Affected:** Navigation+

Please note that the following information has not been incorporated into NAVBLUE databases for cycle 2406

The below information is under state query and has been omitted from NAVBLUE databases until the query has been resolved.

**Source:** Papua New Guinea (AYTB) Flight Supplement 210715 and NOTAM A0054/22

### NOT IN NAVBLUE DATABASES:

Approach procedure NDB/DME (via OKT) CLOUDBREAK – Due to the relocation of Navaid by NOTAM and state has not revised this approach procedure based on the new location of OKT NDB/DME.

is awaiting state information clarification.

**Source:** Sudan AIRAC AIP Amd 01/22

### NOT IN NAVBLUE DATABASES:

Changes to the direction of the segment KAFIA-ALMAM on airway A410 due to an outstanding state query

is awaiting state information clarification.

**Source:** Democratic Republic of Congo AIP AMD 01/23

### NOT IN NAVBLUE DATABASES:

Due to pending state query the updates on page ENR3.5-9 for published airways ATS32 and possible removal of airways ATS29, ATS30, ATS31 have not been actioned in the database.

is awaiting state information clarification.

**Source:** Turkey (LTCG) AIP 231228

### NOT IN NAVBLUE DATABASES:



AN AIRBUS COMPANY

## OMITTED NOTIFICATION BULLETIN

The following SIDs have not been included in NAVBLUE databases due to insufficient state information relating to the arc radials.

BAVT1M  
BAVT1U  
MILQ1U  
PIXA1M  
PIXA1U

is awaiting state information clarification.

**Source:** Switzerland (LSMP) MIL FLIP 240321

### **NOT IN NAVBLUE DATABASES:**

RNP RWY 05 has not been included in NAVBLUE databases due to missing publication data.

is awaiting state information clarification.

**Source:** Japan (RJFZ) AIRAC AIP AMD 5-24

### **NOT IN NAVBLUE DATABASES:**

The TACAN RWY 07 Approach has not been included in NAVBLUE databases due to discrepancies with the coordinates of UPGUN and VABLA.

is awaiting state information clarification.

**Source:** Lithuania NOTAM A2200/24

### **NOT IN NAVBLUE DATABASES:**

Due to a state query the following hold IRKAL/EY (Pattern 4) 0.83 Mach was not suspended.

is awaiting state information clarification.