



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2412-09E

Notification Published date: 04-12-2024

Product Affected: Navigation+

AIRAC Cycle: 2412

Effective Date: 28-11-2024

Region: MES

Country: Oman

Subject: SALALAH (OOSA) - SIDs DAXAM 1R, DAXAM 1V, LADAR 1R & SILTA1R

Source: AIP 240905

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2412

SALALAH (OOSA)

CAUTION: The following errors have been found in NAVBLUE databases.

The Speed restriction of 220kts after the initial climb is missing from DAXAM 1R, DAXAM 1V, LADAR 1R & SILTA 1R SIDs

These changes will be incorporated in NAVBLUE databases for cycle 2413