



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2413-05E

Notification Published date: 22-01-2025

Product Affected: Navigation+

AIRAC Cycle: 2413

Effective Date: 26-12-2024

Region: EUR

Country: Greece

Subject: MITILINI / ODYSSEAS ELYTIS (LGMT) - Incorrect holding pattern course

Source: AIP 250123

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2413

MITILINI / ODYSSEAS ELYTIS (LGMT)

CAUTION: For the VORDME RWY14 approach, the HM Path Terminator at LSV has an incorrect course coded in **NAVBLUE** databases. The correct course should read 126°

These changes will be incorporated in NAVBLUE databases for cycle 2502