



# **JEPPESEN®**

## **NavData® Alert**

**!! URGENT !!**

**Date:** 14 July 2026  
**Subject:** Addis Ababa, Ethiopia  
Bole Intl (HAAB)  
Multiple procedures  
Cycle 2607

***Procedures information missing***

Jeppesen NavData for cycle 2607, effective 9 July 2026, contains incorrect data for Bole Intl; Addis Ababa, Ethiopia (HAAB). Ethiopia SUP 001-26 (**effective 13 July 2026**) was received after the ICAO specified date for aeronautical information publication and contains revised procedure information, which could not be incorporated in time.

Approach procedures: **ILS Y Rwy 25L**, **LOC Y Rwy 25L**, **ILS Z Rwy 25L** and **LOC Z Rwy 25L** are missing from the database.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO  
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2608, effective 6 August 2026. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
**Support Portal:** [digitalsuccess.jeppesen.com](https://digitalsuccess.jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

HAAB\_2607