



JEPPESSEN[®]

NavData[®] Alert

!! URGENT !!

Date: 11 August 2026

Subject: Tindal, Northern Territory, Australia
Tindal (YPTN)
TACAN Rwy 14
Cycle 2608

Procedure information incorrect

Jeppesen NavData for cycle 2608, effective 6 August 2026, contains incorrect data for Tindal, Northern Territory, Australia (YPTN). NOTAMs C0224/26 and C0225/26 published 8 August 2026, establish changes for TACAN Rwy 14 (effective 07 August 26).

The following changes apply to **TACAN Rwy 14** procedure:

- Altitude over fix **FT14** should read **at or above 2070'**.
- Altitude over fix **40TAC** should read **at or above 1430'**.
- **MT14** fix position changed to **1.9 TDL** and should read **S 14° 29' 48.37" E 132° 21' 18.79"**
- **VNAV angle** should read **3.00°**

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2609, effective 3 September 2026. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

YPTN_2608