



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 8 May 2026

Subject: Anisakan, Myanmar
Anisakan (VYAS)
VOR Rwy 21
Cycle 2605

Procedure information incorrect

Jeppesen NavData for cycle 2605, effective 14 May 2026 contains incorrect data for Anisakan, Myanmar (VYAS). Myanmar SUP 001-26 (**effective 14 May 2026**) was received after the ICAO specified date for aeronautical information publication and contains procedure information, which could not be incorporated in time.

VOR/DME “ASN” and procedure **VOR Rwy 21** are missing from the database.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2606, effective 11 June 2026. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jepesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

VYAS_2605